

Ecodora Srl Via Marangoni 33, 36022 S. Zeno di Cassola (VI) Italy Tel. +39 0424 570891 info@ecodora.com

P/N 0E38091

Check valve with connection for 1.1/4" flexible hose and G 1" (m) thread to be applied to the tank discharge cock

SECTORS OF USE

Agriculture, Automotive, Cleaning, Building and road construction, Industry, Mining, Lube trucks and transports

FEATURES

